

ColC

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
Gen NAKAMURA) Examiner: E. L. Frank
Application No.: 10/044,937) Group Art Unit: 2125
Filed: January 15, 2002	·)
For: SEMICONDUCTOR MANUFACTURING APPARATUS) January 11, 2005 :
U.S. Patent No. 6,810,299 B2) :)
Issued: October 26, 2004	Certificate JAN 2 1 2005
Commissioner for Patents	JAN 2 1 2005
P.O. Box 1450	of Correction
Alexandria, VA 22313-1450	

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

Patentee requests that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes and mistakes of a minor nature which are not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

01/12/2005 NNGUYEN2 00000028 6810299

01 FC:1811

100.00 OP

Attention: Certificate of Correction Branch

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for that purpose.

Patentee's undersigned attorney may be reached in our Washington, D.C. Office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,

Attorney for Patentee Steven E. Warner

Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SEW/eab

DC_MAIN 188974v1

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,810,299 B2

DATED: October 26, 2004

INVENTOR(S): Gen NAKAMURA

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE COVER PAGE:

In item "(57) ABSTRACT," line 2, the first occurrence of "light" should read -- light of -- and line 3, "source" should read -- source. --.

COLUMN 6:

Line 36, "In the" should read -- In --.

COLUMN 7:

Line 34, "75 to" should read -- 750 to --.

COLUMN 9:

Line 67, "z driving" should read -- Z driving --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,810,299 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82) No. of add'l. copies @ 30¢ per page



Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,810,299 B2

DATED: October 26, 2004

INVENTOR(S): Gen NAKAMURA

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Line 62, "etc.)" should read -- etc.). --

COLUMN 11:

Line 63, "only on" should read -- only one --.

COLUMN 12:

Line 45, "items." should read -- item, --.

COLUMN 13:

Line 38, "there" should read -- their --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,810, 299 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82) No. of add'l. copies @ 30¢ per page



Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.: 6,810, 299 B2

DATED: October 26, 2004

INVENTOR(S): Gen NAKAMURA

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14:

Line 31, "taken in" should read -- taken-in --.

Line 67, "said" should read -- said --.

COLUMN 15:

Line 9, "taken in" should read -- taken-in --.

Line 12, "software-provides" should read -- software provides --.

COLUMN 16:

Line 26, "Networks," should read -- Network, --.

Line 39, "semiconductor" should read -- the semiconductor --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,810, 299 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82) No. of add'l. copies @ 30¢ per page

⇒__